EndZone

Disassembly Instructions

Spec manufactures End Zone tables from 30" to 36" deep, up to 96" in length as standard. The ends can be either Plinth End Panels or 2" End Panels.

Weights based on a 30"W x 72"L x 39"H, with 2" End Panels.

Recyclable Mate	erial (lbs) 🗳
Steel	21.32
Aluminum	10.09
Wood	128.44
Total Weight	159.85

Tools: Phillips or Robertson screwdriver, box cutter knife, hammer or rubber mallet, pliers.

Skill Set: Good manual dexterity.
Estimated Time: 18 min per credenza.

Steps:

1. Power Supply Trough & Vertical Wire Manager – 1 min.

On the underside of the table, identify the power supply trough and locate the fasteners that connect it to the rectangular table panels. Get help holding the trough in place while unfastening screws. Once detached from the panels, carefully lower the trough. If Vertical Wire Manager is available, remove the doors, manually, then remove fastening screws.

2. Access Panel - 4min

Locate and remove the access panel by pushing the top. At the top edge of the opening, locate the magnetic closing mechanism. Unfasten screws with the required screwdriver and remove mechanism. Remove the metal plate from panel.

3. Top - 2min

Identify the base top on the underside of the table top.
Locate fasteners (number may vary between tables). With the required screwdriver unfasten screws. With the assistance of another person, lift the table top off the base.

4. Corner Components - 2min

Identify the plate brackets spanning the inner corners of the base. With the required screwdriver, remove the four outer fastening screws on the bracket. With the required 1/4" Hex key, remove the center fasteners. Detach bracket from base frame. Slide the aluminum corner component upward to separate from the remaining base construction. Tilt the corner component vertically to retrieve the small fastening plate. Repeat this process to the remaining corners.

5. Glides - 5min

Flip the corner component upside down to gain access to feet glides. With pliers, firmly grasp the glide and unscrew counter clockwise until free. Repeat process to all remaining corner components.

6. Feet / Kick plate - 5min

Feet - Locate the 6 fasteners on the connecting plate of the foot. Unfasten screws and remove foot. Repeat procedure to all remaining feet.

Kick plate - Identify the L brackets around the inside perimeter of the kick plate. With the required screwdriver, remove fasteners. Detach L bracket from the kick plate, repeat process to all remaining L brackets. Lift the kick plate.







